


通告 Notice

大棠燒烤區 1 號場近小食亭加水站由於機件故障，需要等候更換零件，因而暫停開放給公眾使用，直至另行通知。不便之處，敬請原諒。

Due to mechanical failure and the pending replacement of parts, water filling station at Tai Tong Barbecue Site No.1 near the food kiosk is closed until further notice. We apologise for any inconvenience caused.



漁農自然護理署
Agriculture, Fisheries and
Conservation Department